



CT64 Chemosmart


TRACE CHEMOTHERAPY WASTE | INSTRUCTIONS FOR USE














Remember

STRICTLY NO LOOSE SHARPS to be deposited into this collector.

ALWAYS WASH HANDS after handling waste.

DO NOT OVERFILL maximum gross weight 40lbs.